



Software Release Notes

Fisker Ocean Application

Version 2.5.2

April 2026

The following document provides a list of changes for the onboard Fisker software package.

What's New

Hollywood Mode w/Wi-Fi

- Screen rotation to display the Fisker Infotainment system in true landscape mode using phone hotspot
- Supports an internet connection using your phone's mobile hotspot
- Enables media playback including YouTube & Amazon Prime Video
**performance may be affected by Fisker's older browser (OV is looking to update this in a future release)*

Improvements & Fixes

HVAC Controls

Users can easily launch the HVAC menu using the fan icon on the Touch Bar below the screen.

- Short key press < 1.5 seconds: toggles climate power on or off
- Long key press > 1.5 seconds: opens the climate control panel

Temperature Controls

Users can easily enable or disable Sync or HVAC modes using the temp icon on the Screen.

- Short key press < 1.5 seconds: toggles temperature Sync mode on/off
- Long key press > 1.5 seconds: toggles between auto and manual HVAC mode

VSP Chime Persistence

- Fixes an issue where a custom chime may not be persistent after the vehicle has been sleeping
- The fix must be used in conjunction with 24hr standby mode

HVAC Settings Persistence

- Fixes an issue where the Manual or Auto HVAC settings could be lost after the vehicle has been sleeping. Now the combination of temp, AC, and auto/manual will be maintained
- This fix is recommended to be used in conjunction with 24hr mode

HVAC for Cabin Temperature

- Fixed an issue where the display for sync'd temperature settings was not correctly reported (RHD only)

HVAC for Defroster Temperature

- Fixed an issue where climate screen and button bar are not consistent

O Loop Application BLE

- Stability improvements

OS Versioning Improvements

- Allow for a segmented version e.g. 1.0.0

Regenerative Braking

- Fixed an issue where regen braking changes may not take effect

Resource Optimization	Improved background app resource utilization
-----------------------	--

Known Limitations

OEM Timing Issues	Some issues are the result of timing during the vehicle boot-up process. When any service starts slow, it can result in a temporary situation where the user profile has not loaded (using 24hr mode minimizes this). It resolves itself once all services are started.
VSP Customization	There is a 24 hr mode dependency when setting any custom sounds

Installation Notes

Requirements & Timing	The download and installation of the update will vary based on your internet speed. Whenever possible, you should use wi-fi to accelerate the process. - HV > 20% 12v Battery > 85% - The OS upgrade files may take up to 30 minutes to download - The actual installation may take up to 30 minutes after the user has tapped the 'confirmation' button
-----------------------	--