



## Software Release Notes

### Fisker Ocean Application

Version 2.6.1

March 2026

The OS 2.6.1 release is considered a maintenance release and is focused on making fixes to the previous release (2.6.0) and minor enhancements. New features or major enhancements are reserved for full releases.

For additional information, FAQs, or to see what we have to offer visit us at: [Ocean Loop](#)

## Improvements

The improvements listed below are applicable to all Fisker Oceans, but especially useful when using Autokit.

|                      |                                                                                                                                                                                                                                                                                                                                                                                                    |
|----------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PKC 22               | <p>This release includes the latest PKC. It provides a greatly enhanced experience for all Fisker owners.</p> <ul style="list-style-type: none"><li>• Key Fob - improved battery life</li><li>• Key Fob - improved responsiveness</li><li>• Key Fob - improved reliability</li><li>• Key Fob - double-press for California mode</li><li>• Key Fob - double-press to open/close the trunk</li></ul> |
| HVAC Controls        | <p>Users can easily launch the HVAC menu using the fan icon on the Touch Bar below the screen.</p> <ul style="list-style-type: none"><li>• Short key press &lt; 1.5 seconds: toggles climate power on or off</li><li>• Long key press &gt; 1.5 seconds: opens the climate control panel</li></ul>                                                                                                  |
| Temperature Controls | <p>Users can easily enable or disable Sync or HVAC modes using the temp icon on the Screen.</p> <ul style="list-style-type: none"><li>• Short key press &lt; 1.5 seconds: toggles temperature Sync mode on/off</li><li>• Long key press &gt; 1.5 seconds: toggles between auto and manual HVAC mode</li></ul>                                                                                      |

## Fixes

The fixes listed below are applicable to all Fisker Oceans.

|                           |                                                                                                                                                                                                                                                                                                           |
|---------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| PKC 22                    | <ul style="list-style-type: none"><li>• Crash with more than 2 BLE devices connected at the same time (includes both keys and phones)</li><li>• Resolves issues when the NFC door or dash readers are damaged; allowing the user to continue accessing and driving their Ocean</li></ul>                  |
| VSP Chime Persistence     | <ul style="list-style-type: none"><li>• Fixes an issue where a custom chime may not be persistent after the vehicle has been sleeping</li><li>• The fix must be used in conjunction with 24hr standby mode</li></ul>                                                                                      |
| HVAC Settings Persistence | <ul style="list-style-type: none"><li>• Fixes an issue where the Manual or Auto HVAC settings could be lost after the vehicle has been sleeping. Now the combination of temp, AC, and auto/manual will be maintained</li><li>• This fix is recommended to be used in conjunction with 24hr mode</li></ul> |

## Software Release Notes

### Known Limitations

|                    |                                                                                                                                                                                                                                                                                                                         |
|--------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| O Loop Application | <ul style="list-style-type: none"><li>Using OS 2.6.1 requires O Loop v.1.2.1 (due to PKC requirements)</li></ul>                                                                                                                                                                                                        |
| OEM Timing Issues  | <ul style="list-style-type: none"><li>Some issues are the result of timing during the vehicle boot-up process. When any service starts slow, it can result in a temporary situation where the user profile has not loaded (using 24hr mode minimizes this). It resolves itself once all services are started.</li></ul> |

### Installation Notes

|                       |                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|-----------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Requirements & Timing | <p>The download and installation of the update will vary based on your internet speed. Whenever possible, you should use wi-fi to accelerate the process.</p> <ul style="list-style-type: none"><li>HV &gt; 20%</li><li>12v Battery &gt; 85%</li><li>The OS upgrade files may take up to 30 minutes to download</li><li>The actual installation may take up to 30 minutes after the user has tapped the 'confirmation' button</li></ul> |
| File Downloads        | <ul style="list-style-type: none"><li>Users can monitor the download with the new progress bar that was implemented as part of OS 2.6 - go to Settings &gt;&gt; Software</li></ul>                                                                                                                                                                                                                                                      |